

032.0 ASSEMBLY OF SIDE LIGHTS - MONTAGGIO LUCI LATERALI



Side lights

Before gluing, bend the strips by curving them up to be perpendicular to the bodywork.

To glue, after cleaning the surface with alcohol, put a small layer of "bostik", wait 10 minutes then glue it with the wire to the paramotor. The strip with the longest cable is on the right. Bring the cables under the left-hand storage box, where the power-on plug is located on.

Luci laterali

Prima di incollare, piegare le strisce curvandole fino ad essere perpendicolari alla carrozzeria.

Per incollare, dopo aver pulito la superficie con alcol, mettere un piccolo strato di "bostik", attendere 10 minuti poi incollare con il filo verso il paramotore. La striscia con il cavo più lungo è a destra. Portare e collegare i cavi sotto il portaoggetti di sinistra, dove si trova lo spinotto di alimentazione funzionante a chiave on.





sito ecommerce:

www.alidoro.store

Catalogo sfogliabile online ita: www.kappasystems.srl/alidoro.asp

ALI D'ORO NUMERO VERDE

800 942994